

Bunker Hill Rd Culvert (Bear Swamp Brook, TOA) - Pictures before work to protect downstream headwall from erosion and scour. Photos taken by Wetlands Agent 03.11.2024.



*1- View of brook flowing downstream from crossing.*



Bunker Hill Rd Culvert (Bear Swamp Brook, TOA) - Pictures before work to protect downstream headwall from erosion and scour. Photos taken by Wetlands Agent 03.11.2024.



2 - View of downstream side of headwall--erosion is clearly visible.



Bunker Hill Rd Culvert (Bear Swamp Brook, TOA) - Pictures before work to protect downstream headwall from erosion and scour. Photos taken by Wetlands Agent 03.11.2024.



*3 - View of downstream side of crossing, where work will take place. Erosion is clearly visible on the sides of the headwall.*



Bunker Hill Rd Culvert (Bear Swamp Brook, TOA) - Pictures before work to protect downstream headwall from erosion and scour. Photos taken by Wetlands Agent 03.11.2024.



4 - View of downstream side of crossing



Bunker Hill Rd Culvert (Bear Swamp Brook, TOA) - Pictures before work to protect downstream headwall from erosion and scour. Photos taken by Wetlands Agent 03.11.2024.



5 - View of upstream side of crossing.



Bunker Hill Rd Culvert (Bear Swamp Brook, TOA) - Pictures before work to protect downstream headwall from erosion and scour. Photos taken by Wetlands Agent 03.11.2024.



6 - View of upstream side of crossing



Bunker Hill Rd Culvert (Bear Swamp Brook, TOA) - Pictures before work to protect downstream headwall from erosion and scour. Photos taken by Wetlands Agent 03.11.2024.



7 - View of upstream side of crossing



Bunker Hill Rd Culvert (Bear Swamp Brook, TOA) - Pictures before work to protect downstream headwall from erosion and scour. Photos taken by Wetlands Agent 03.11.2024.



8 - View of downstream side of crossing.