



*1- Looking at the southern corner of the lake wall. This area is proposed to be restacked.*





*2- A view of the southern corner of the wall where it turns west into the property and away from the lakeshore. This area is proposed to be restacked.*





*3- Looking down at the southern corner of the lake wall. This end is proposed to be restacked.*





4- A view of the north section of the wall-- one of the areas proposed to be restacked.





*5- View of the center area of the lake wall. This area is proposed to be re-pointed with mortar, but does not need to be restacked.*





*6- View of wall from the shoreline at the north end of property.*





7- Looking along wall from the north end of the property. The crumbled wall in the foreground is proposed to be restacked.





*8- View of wall, looking northeast from lawn of 1 Lakeside Dr.*