

Photos joined by large boulder. Intermittent stream highlighted by blue dashed arrow



Photo #3 submitted on April 1, 2020 regarding complaint of an IWW violation at #129 Hebron Rd, Andover, CT Hebron Road is visible at the top of the photo. #129 Hebron Road parcel is to photo left; neighboring property, #125 Hebron Road is to photo right.



Photo #4 taken by IWWC chair on April 6, 2020.

#129 Hebron Road residence is shown in the upper right of the photo. The intermittent stream flows from A to B. Removal of material (trenching) is shown occurring across the stream int eh center of the photo. A string (red arrow), presumably to guide digging of the trench line, is seen above the path of the trench.



Photo #5 – Taken 04/06/2020 by IWWC Chair from #125 Hebron Road property line.

Intermittent stream is observed in the foreground and flows from left to right in the photo.

Removal of material along a linear path (e.g trench) is observed from the lower left of the photo extending up towards the upper right of the photo (towards Hebron Rd). Placement of material is observed adjacent to the area of removal.