

1- View of existing stone lake wall on the southern side of the property. Dock to be removed and wall to be rebuilt is in the red box.



2 View along property line at southern edge of 3 Lakeside Drive. Wall and dock are inside the red box, and the existing sand beach is to the left of the box.

IWWC21-27- 3 Lakeside Drive (McCullough) Pictures from Agent Site Visit 01-10-2022



3- Looking at the northwest corner of 3 Lakeside Drive.

IWWC21-27- 3 Lakeside Drive (McCullough) Pictures from Agent Site Visit 01-10-2022



4- Looking south from the northern corner of the 3 Lakeside Drive property. The existing sand beach is in the center of the photo.

IWWC21-27- 3 Lakeside Drive (McCullough) Pictures from Agent Site Visit 01-10-2022



5- View of the existing stone wall (in poor condition) at the northern edge of the property.

IWWC21-27- 3 Lakeside Drive (McCullough) Pictures from Agent Site Visit 01-10-2022



6- View of the northwest corner of 3 Lakeside Drive. the northern section of stone wall is in the red box.