

IWWC 23-07 – 760 East St, Nolette – Pictures of property after heavy rain on July 2, 2023. Submitted by W. Nolette on 07.05.2023.



*1- View of pond outlet after heavy rainfall.*



IWWC 23-07 – 760 East St, Nolette – Pictures of property after heavy rain on July 2, 2023. Submitted by W. Nolette on 07.05.2023.



*2- View of pond, looking south toward Hurst Farm (746 East St). Pond inlet is visible in center of photo.*



IWWC 23-07 – 760 East St, Nolette – Pictures of property after heavy rain on July 2, 2023. Submitted by W. Nolette on 07.05.2023.



*3- View of pond outlet and lack of flow through outlet and stream after heavy rainfall.*



IWWC 23-07 – 760 East St, Nolette – Pictures of property after heavy rain on July 2, 2023. Submitted by W. Nolette on 07.05.2023.



*4- View of western edge of pond, near newly constructed (and currently dammed) outlet created by the homeowner. Pond is unable to properly drain through the original outlet and stream, and has started to flow over the temporary dam.*



IWWC 23-07 – 760 East St, Nolette – Pictures of property after heavy rain on July 2, 2023. Submitted by W. Nolette on 07.05.2023.



5- Another view of the breached temporary dam at the western edge of the pond. Homeowner has since repaired the dam and extended it by filling more of the downstream channel with rocks and soil.