



The photo above is of the wetland crossing to the west of the shooting range near the center of the ASC Timber Harvest Map. The culvert had been installed previously and was used for a similar harvest 15 years ago. Timbers have been placed on top of the culvert to protect it during logging operations.





The photo above is of the same wetland crossing to the west of the shooting range near the center of the ASC Timber Harvest Map. The culvert had been installed previously and was used for a similar harvest 15 years ago. Timbers have been placed on top of the culvert to protect it during logging operations.





This photo is of the other wetland crossing located on the southeast corner of the parcel, near the Airline Trail.





This photo is also of the other wetland crossing located on the southeast corner of the parcel, near the Airline Trail. The dark-colored culvert pipe is barely visibly in the center-left of the photo.