



*1- View of wetlands crossing, looking west toward Pine Ridge Drive. Taken by Wetlands Agent on 09-27-2022.*



IWWC #20-36 26 Old Farms Road (Loteczka, Correia). Pictures from July-September Agent Site Visits.



*2- View of downstream side of open-bottom culvert. Pine Ridge Drive is toward the upper left corner of the photo. Taken by Wetlands Agent 09-27-2022*



IWWC #20-36 26 Old Farms Road (Loteczka, Correia). Pictures from July-September Agent Site Visits.



3- View of downstream (southern) side of open bottom culvert. Taken by Wetlands Agent 09-27-2022.



IWWC #20-36 26 Old Farms Road (Loteczka, Correia). Pictures from July-September Agent Site Visits.



4- View of crossing from downstream side. Taken by Wetlands Agent 09-07-2022.



IWWC #20-36 26 Old Farms Road (Loteczka, Correia). Pictures from July-September Agent Site Visits.



5- Looking north through round culvert.. Taken by Wetlands Agent 08-22-2022.



IWWC #20-36 26 Old Farms Road (Loteczka, Correia). Pictures from July-September Agent Site Visits.



*6- Looking north through cast-in-place culvert. Taken by Wetlands Agent 08-22-2022.*





*7- View of crossing looking north. Pine ridge drive is to the left of the photo. The center of the stream channel was preserved in order to retain as much undisturbed soil as possible. Taken by Wetlands Agent 07-13-2022.*



IWWC #20-36 26 Old Farms Road (Loteczka, Correia). Pictures from July-September Agent Site Visits.



*8- View of wetlands crossing site, after clearing and grading and before construction of crossing. Taken by Wetlands Agent 07-06-2022..*