



*1- View of existing trail down slope, looking west toward Hop River. Erosion is visible in the foreground. Bench is to the right of photo.*





*2- View of proposed stair location, looking west toward Hop River. Bench is behind and slightly to the left.*





3- View of proposed stair location, looking west toward Hop River. The red rectangle indicates the location of the proposed stairs. Bench is behind and slightly to the left.





*4- View looking uphill at proposed stair location. Stairs will be placed between the large rock and the tree in foreground.*