


1- Looking downhill toward area of wall to be reconstructed.




2- Looking downhill toward area of wall to be reconstructed.



3- Looking west along section of wall to be reconstructed.




4- View of eastern corner of existing wall




⁵⁻ Looking downhill at eastern corner of wall.



6- Looking north along southwestern edge of the wall section wall to be reconstructed.



7- Southwestern edge of wall reconstruction will end near tree stump shown near the center of the picture.



8- View of the top of the wall to be reconstructed.



9- Looking downhill toward wall. Equipment will access the wall through this area.