



*Project #1, Photo #1- View of new sand deposited over existing beach area. Beach area originally approved by IWWC on May 10, 1993. Work was stopped after property owner was made aware of the need for IWWC approval.*



*Project #1, Photo #2- Another view of new sand deposited over existing beach area. Beach area originally approved by IWWC on May 10, 1993. Work was stopped after property owner was made aware of the need for IWWC approval.*





*Project #2, Photo #1- View of existing dock. "L" part was deteriorated and has already been removed. Proposed dock will be L-shaped, similar to the existing dock prior to the partial deconstruction.*





*Project #2, Photo #2- Another view of the dock, as seen from the lake bed.*