IWWC22-12\_Lot 22 (409) Lake Rd (Connelly) - Pictures of Agent Visit 10-19-2023



1- View of rain garden, looking south from driveway.



2- View of rain garden, as seen from driveway. Erosion control fencing should be removed when adequate ground cover has been established.

IWWC22-12\_Lot 22 (409) Lake Rd (Connelly) - Pictures of Agent Visit 10-19-2023




3- View of downstream (south) side of wetlands crossing.




4- View of inlet on upstream (north) side of wetlands crossing.



5- View of inlet on upstream (north) side of wetlands crossing.



6- View of upstream (north) side of wetlands crossing.



7- Looking east from wetlands crossing.

IWWC22-12\_Lot 22 (409) Lake Rd (Connelly) - Pictures of Agent Visit 10-19-2023



8- View of rain garden, as seen from driveway.