

1 Looking at wetlands to the north of the proposed crossing area. The property of 411 Lake Road is in the background.



2 Another view of the wetlands to the north of the proposed crossing area. The property of 411 Lake Road is in the background.



3- Close-up view of "streambed" area of wetlands crossing, looking north toward 411 Lake Road.



4 View of property, looking west from the stone wall in the center of the property toward Lake Road. Wetlands are near the center of the photograph.



5 Standing at Wetlands Flag (#16 on map?). Looking west toward Lake Road.



6 Standing near the center of the wetlands crossing area, looking toward Lake Road.



7 View of "streambed" at the center of wetland crossing area. Area was relatively dry and solid at the time the photo was taken.



8 View of wetlands, looking northwest toward lake road and 411 Lake Road.



9 Another view of the wetlands crossing area, looking south (toward 407 Lake Road) from the approximate crossing area. The "streambed" is visible in the foreground and center.



10 View of Property marker near CL+P pole #35. Lake Road is behind me.



11 View of CL+P Pole #36 (Marked 37 on map), located near the southern corner of the property.



12 Another look at the wetlands and the intermittent watercourse channel to the north of the proposed crossing area. The property of 411 Lake Road is in the background.