

IWWC #23-16, 357 Lake Rd. (Grimaldi) – Pictures of shed (garage) taken by Agent 09.28.2023



1- View of western side of garage. Intermittent stream is located behind the garage.





2- View of house foundation/gutter (?) drains. Intermittent stream is located to the left of the photo, and runs into the background (top) of the photo.





3- View of the intermittent stream channel that runs behind (south of) the garage.





4- View of south side of garage. I was standing next to the intermittent stream channel. The house is visible to the right.





5- View of south side of garage, as seen from near the intermittent stream channel.





6- View of south side of garage, as seen from near the intermittent stream channel.





*7- View of wetland area and intermittent stream channel behind (south of) the garage.*



IWWC #23-16, 357 Lake Rd. (Grimaldi) – Pictures of shed (garage) taken by Agent 09.28.2023



8- View of western side of garage. Intermittent stream is behind the garage (in the background of the photo).