

IWWC #23-17JR, 63 Bunker Hill Road. Photos of wetland crossings, taken by Agent on 10.10.2023



*1- View of wetlands crossing #1, looking south toward Bunker Hill Rd.*

IWWC #23-17JR, 63 Bunker Hill Road. Photos of wetland crossings, taken by Agent on 10.10.2023



*2- View of wetlands crossing #1, looking north.*

IWWC #23-17JR, 63 Bunker Hill Road. Photos of wetland crossings, taken by Agent on 10.10.2023



*3- View of wetlands crossing #2, looking north.*

IWWC #23-17JR, 63 Bunker Hill Road. Photos of wetland crossings, taken by Agent on 10.10.2023



*4- View of stream channel in center of wetlands crossing #2. Skid trail crosses from left to right in photo.*

IWWC #23-17JR, 63 Bunker Hill Road. Photos of wetland crossings, taken by Agent on 10.10.2023



*5- View of downstream side of wetlands crossing #2, looking west.*

IWWC #23-17JR, 63 Bunker Hill Road. Photos of wetland crossings, taken by Agent on 10.10.2023



6- View of wetlands crossing #2, looking south toward crossing.

IWWC #23-17JR, 63 Bunker Hill Road. Photos of wetland crossings, taken by Agent on 10.10.2023



*7- View of wetland crossing #2, looking southeast and downstream. Crossing area is on the left side of the photo.*

IWWC #23-17JR, 63 Bunker Hill Road. Photos of wetland crossings, taken by Agent on 10.10.2023



8- View of wetland crossing #2, looking north.

IWWC #23-17JR, 63 Bunker Hill Road. Photos of wetland crossings, taken by Agent on 10.10.2023



*9 - View of wetlands crossing #3, looking west.*

IWWC #23-17JR, 63 Bunker Hill Road. Photos of wetland crossings, taken by Agent on 10.10.2023



10 - View of wetlands crossing #3, looking east.