



*1- View of watercourse flowing north away from propane tank platform.*





*2-Photo taken from existing platform, looking east toward community center.*





3- Photo taken from parking lot, looking north toward brook. Area to be filled is in foreground, and the existing propane tanks are to the left.





4- View of cleared work area, looking north from the parking lot. Invasive plants in the area have been removed, and vines have been cut or removed (where possible) from trees. Mulch berms have been placed for erosion control during work.





5- View from parking lot, looking west toward existing propane tanks and new tank location.





*6- View from existing propane tank pad, looking northwest toward downstream section of brook.*